

OM-2223

190 969R

January 2005

Processes



Multiprocess Welding

Description






Arc Welding Power Source

CE

Dimension 1000/1250





OWNER'S MANUAL

From Miller to You

Thank you and congratulations on choosing Miller. Now you can get the job done and get it done right. We know you don't have time to do it any other way.

That's why when Niels Miller first started building arc welders in 1929, he made sure his products offered long-lasting value and superior quality. Like you, his customers couldn't afford anything less. Miller products had to be more than the best they could be. They had to be the best you could buy.

Today, the people that build and sell Miller products continue the tradition. They're just as committed to providing equipment and service that meets the high standards of quality and value established in 1929.

This Owner's Manual is designed to help you get the most out of your Miller products. Please take time to read the Safety precautions. They will help you protect yourself against potential hazards on the worksite.



Miller is the first welding equipment manufacturer in the U.S.A. to be registered to the ISO 9001:2000 Quality System Standard.

We've made installation and operation quick and easy. With Miller you can count on years of reliable service with proper maintenance. And if for some reason the unit needs repair, there's a Troubleshooting section that will help you figure out what the problem is. The parts list will then help you to decide the exact part you may need to fix the problem. Warranty and service information for your particular model are also provided.

Miller Electric manufactures a full line of welders and welding related equipment. For information on other quality Miller

products, contact your local Miller distributor to receive the latest full line catalog or individual catalog sheets. To locate your nearest distributor or service agency call 1-800-4-A-Miller, or visit us at www.MillerWelds.com on the web.



Working as hard as you do – every power source from Miller is backed by the most hassle-free warranty in the business.



TABLE OF CONTENTS

SECTIO	N 1 – SAFETY PRECAUTIONS - READ BEFORE USING	1
1-1.	Symbol Usage	1
1-2.	Arc Welding Hazards	1
1-3.	Additional Symbols For Installation, Operation, And Maintenance	3
1-4.	California Proposition 65 Warnings	3
1-5.	Principal Safety Standards	4
1-6.	EMF Information	4
SECTIO	N 2 – CONSIGNES DE SÉCURITÉ – À LIRE AVANT UTILISATION	5
2-1.	Signification des symboles	5
2-2.	Dangers relatifs au soudage à l'arc	5
2-3.	Autres symboles relatifs à l'installation, au fonctionnement et à l'entretien de l'appareil	7
2-4.	Principales normes de sécurité	8
2-5.	Information sur les champs électromagnétiques	8
SECTIO	N 3 – DEFINITIONS	9
3-1.	General Precautionary Label	9
3-2.	Input Connection Label	10
3-3.	Electric Shock And Airflow Label	10
3-4.	Nameplate Safety Symbols	10
3-5.	Manufacturer's Rating Label For CE Products	11
3-6.	Symbol Definitions	11
SECTIO	N 4 – INSTALLATION	12
4-1.	Specifications	12
4-2.	Duty Cycle And Overheating	12
4-3.	Volt-Ampere Curves	13
4-4.	Selecting A Location	14
4-5.	Dimensions And Weights	15
4-6.	Tipping	16
4-7.	115 VAC Receptacle And Circuit Breakers	16
4-8.	Weld Output Terminals And Selecting Cable Sizes	17
4-9.	Remote 14 Receptacle And Terminal Strip 1T Information	17
4-10.	Connecting Remote Control	18
4-11.	Electrical Service Guide	19
4-12.	Placing Jumper Links	19
4-13.	Connecting Input Power	20
SECTIO	N 5 – OPERATION	22
5-1.	Controls	22
SECTIO	N 6 – MAINTENANCE & TROUBLESHOOTING	24
6-1.	Routine Maintenance	24
6-2.	Fuse F1	24
6-3.	Troubleshooting	
SECTIO	N 7 – ELECTRICAL DIAGRAMS	26
SECTIO	N 8 – PARTS LIST	28
OPTION	IS AND ACCESSORIES	
WADDA	NTV	

Declaration of Conformity For European Community (CE) Products

NOTE



This information is provided for units with CE certification (see rating label on unit.)

Manufacturer's Name: Miller Electric Mfg. Co.

Manufacturer's Address: 1635 W. Spencer Street Appleton, WI 54914 USA

Declares that the product: DimensionTM 1000/1250

conforms to the following Directives and Standards:

Directives

Electromagnetic compatibility Directives: 89/336/EEC, 92/31/EEC

Low Voltage Directive: 73/23/EEC

Machinery Directives: 89/392/EEC, 91/368/EEC, 93/C 133/04, 93/68/EEC

Standards

Safety Requirements for Arc Welding Equipment part 1: EN 60974-1: 1990

Arc Welding Equipment Part 1: Welding Power Sources: IEC 974-1 (April 1998 – Draft revision)

Degrees of Protection provided by Enclosures (IP code): IEC 529: 1989

Insulation coordination for equipment within low-voltage systems: Part 1: Principles, requirements and tests: IEC 664-1: 1992

Electromagnetic compatibility (EMC) Product standard for arc welding equipment: EN50199: August 1995

European Contact: Danilo Fedolfi, Managing Director

ITW WELDING PRODUCTS S.r.I.

Via Privata Iseo 6/E 20098 San Giuliano Milanese, Italy

Telephone: 39(02)98290-1

Fax: 39(02)98290-203

SECTION 1 – SAFETY PRECAUTIONS - READ BEFORE USING

som 8/03

1-1. Symbol Usage



Means Warning! Watch Out! There are possible hazards with this procedure! The possible hazards are shown in the adjoining symbols.

▲ Marks a special safety message.

IF Means "Note"; not safety related.



This group of symbols means Warning! Watch Out! possible ELECTRIC SHOCK, MOVING PARTS, and HOT PARTS hazards. Consult symbols and related instructions below for necessary actions to avoid the hazards.

1-2. Arc Welding Hazards

- ▲ The symbols shown below are used throughout this manual to call attention to and identify possible hazards. When you see the symbol, watch out, and follow the related instructions to avoid the hazard. The safety information given below is only a summary of the more complete safety information found in the Safety Standards listed in Section 1-5. Read and follow all Safety Standards.
- ▲ Only qualified persons should install, operate, maintain, and repair this unit.
- ▲ During operation, keep everybody, especially children, away.

ELECTRIC SHOCK can kill.

Touching live electrical parts can cause fatal shocks or severe burns. The electrode and work circuit is electrically live whenever the output is on. The input power circuit and machine internal circuits are also

live when power is on. In semiautomatic or automatic wire welding, the wire, wire reel, drive roll housing, and all metal parts touching the welding wire are electrically live. Incorrectly installed or improperly grounded equipment is a hazard.

- Do not touch live electrical parts.
- Wear dry, hole-free insulating gloves and body protection.
- Insulate yourself from work and ground using dry insulating mats or covers big enough to prevent any physical contact with the work or ground.
- Do not use AC output in damp areas, if movement is confined, or if there is a danger of falling.
- Use AC output ONLY if required for the welding process.
- If AC output is required, use remote output control if present on unit.
- Disconnect input power or stop engine before installing or servicing this equipment. Lockout/tagout input power according to OSHA 29 CFR 1910.147 (see Safety Standards).
- Properly install and ground this equipment according to its Owner's Manual and national, state, and local codes.
- Always verify the supply ground check and be sure that input power cord ground wire is properly connected to ground terminal in disconnect box or that cord plug is connected to a properly grounded receptacle outlet.
- When making input connections, attach proper grounding conductor first double-check connections.
- Frequently inspect input power cord for damage or bare wiring replace cord immediately if damaged – bare wiring can kill.
- Turn off all equipment when not in use.
- Do not use worn, damaged, undersized, or poorly spliced cables.
- Do not drape cables over your body.

- If earth grounding of the workpiece is required, ground it directly with a separate cable.
- Do not touch electrode if you are in contact with the work, ground, or another electrode from a different machine.
- Use only well-maintained equipment. Repair or replace damaged parts at once. Maintain unit according to manual.
- Wear a safety harness if working above floor level.
- Keep all panels and covers securely in place.
- Clamp work cable with good metal-to-metal contact to workpiece or worktable as near the weld as practical.
- Insulate work clamp when not connected to workpiece to prevent contact with any metal object.
- Do not connect more than one electrode or work cable to any single weld output terminal.

SIGNIFICANT DC VOLTAGE exists after removal of input power on inverters.

 Turn Off inverter, disconnect input power, and discharge input capacitors according to instructions in Maintenance Section before touching any parts.



FUMES AND GASES can be hazardous.

Welding produces fumes and gases. Breathing these fumes and gases can be hazardous to your health.

- Keep your head out of the fumes. Do not breathe the fumes.
- If inside, ventilate the area and/or use exhaust at the arc to remove welding fumes and gases.
- If ventilation is poor, use an approved air-supplied respirator.
- Read the Material Safety Data Sheets (MSDSs) and the manufacturer's instructions for metals, consumables, coatings, cleaners, and degreasers.
- Work in a confined space only if it is well ventilated, or while wearing an air-supplied respirator. Always have a trained watchperson nearby. Welding fumes and gases can displace air and lower the oxygen level causing injury or death. Be sure the breathing air is safe.
- Do not weld in locations near degreasing, cleaning, or spraying operations. The heat and rays of the arc can react with vapors to form highly toxic and irritating gases.
- Do not weld on coated metals, such as galvanized, lead, or cadmium plated steel, unless the coating is removed from the weld area, the area is well ventilated, and if necessary, while wearing an air-supplied respirator. The coatings and any metals containing these elements can give off toxic fumes if welded.



ARC RAYS can burn eyes and skin.

Arc rays from the welding process produce intense visible and invisible (ultraviolet and infrared) rays that can burn eyes and skin. Sparks fly off from the weld.

- Wear a welding helmet fitted with a proper shade of filter to protect your face and eyes when welding or watching (see ANSI Z49.1 and Z87.1 listed in Safety Standards).
- Wear approved safety glasses with side shields under your helmet.
- Use protective screens or barriers to protect others from flash and glare; warn others not to watch the arc.
- Wear protective clothing made from durable, flame-resistant material (leather and wool) and foot protection.



WELDING can cause fire or explosion.

Welding on closed containers, such as tanks, drums, or pipes, can cause them to blow up. Sparks can fly off from the welding arc. The flying sparks, hot workpiece, and hot equipment can cause fires and

burns. Accidental contact of electrode to metal objects can cause sparks, explosion, overheating, or fire. Check and be sure the area is safe before doing any welding.

- Protect yourself and others from flying sparks and hot metal.
- Do not weld where flying sparks can strike flammable material.
- Remove all flammables within 35 ft (10.7 m) of the welding arc. If this is not possible, tightly cover them with approved covers.
- Be alert that welding sparks and hot materials from welding can easily go through small cracks and openings to adjacent areas.
- Watch for fire, and keep a fire extinguisher nearby.
- Be aware that welding on a ceiling, floor, bulkhead, or partition can cause fire on the hidden side.
- Do not weld on closed containers such as tanks, drums, or pipes, unless they are properly prepared according to AWS F4.1 (see Safety Standards).
- Connect work cable to the work as close to the welding area as practical to prevent welding current from traveling long, possibly unknown paths and causing electric shock and fire hazards.
- Do not use welder to thaw frozen pipes.
- Remove stick electrode from holder or cut off welding wire at contact tip when not in use.
- Wear oil-free protective garments such as leather gloves, heavy shirt, cuffless trousers, high shoes, and a cap.
- Remove any combustibles, such as a butane lighter or matches, from your person before doing any welding.



FLYING METAL can injure eyes.

- Welding, chipping, wire brushing, and grinding cause sparks and flying metal. As welds cool, they can throw off slag.
- Wear approved safety glasses with side shields even under your welding helmet.



BUILDUP OF GAS can injure or kill.

- Shut off shielding gas supply when not in use.
- Always ventilate confined spaces or use approved air-supplied respirator.



HOT PARTS can cause severe burns.

- Do not touch hot parts bare handed.
- Allow cooling period before working on gun or torch.



MAGNETIC FIELDS can affect pacemakers.

- Pacemaker wearers keep away.
- Wearers should consult their doctor before going near arc welding, gouging, or spot welding operations.



NOISE can damage hearing.

Noise from some processes or equipment can damage hearing.

 Wear approved ear protection if noise level is high.



CYLINDERS can explode if damaged.

Shielding gas cylinders contain gas under high pressure. If damaged, a cylinder can explode. Since gas cylinders are normally part of the welding process, be sure to treat them carefully.

- Protect compressed gas cylinders from excessive heat, mechanical shocks, slag, open flames, sparks, and arcs.
- Install cylinders in an upright position by securing to a stationary support or cylinder rack to prevent falling or tipping.
- Keep cylinders away from any welding or other electrical circuits.
- Never drape a welding torch over a gas cylinder.
- Never allow a welding electrode to touch any cylinder.
- Never weld on a pressurized cylinder explosion will result.
- Use only correct shielding gas cylinders, regulators, hoses, and fittings designed for the specific application; maintain them and associated parts in good condition.
- Turn face away from valve outlet when opening cylinder valve.
- Keep protective cap in place over valve except when cylinder is in use or connected for use.
- Read and follow instructions on compressed gas cylinders, associated equipment, and CGA publication P-1 listed in Safety Standards.

1-3. Additional Symbols For Installation, Operation, And Maintenance



FIRE OR EXPLOSION hazard.

- Do not install or place unit on, over, or near combustible surfaces.
- Do not install unit near flammables.
- Do not overload building wiring be sure power supply system is properly sized, rated, and protected to handle this unit.



FALLING UNIT can cause injury.

- Use lifting eye to lift unit only, NOT running gear, gas cylinders, or any other accessories.
- Use equipment of adequate capacity to lift and support unit.
- If using lift forks to move unit, be sure forks are long enough to extend beyond opposite side of unit.



OVERUSE can cause OVERHEATING

- Allow cooling period; follow rated duty cycle.
- Reduce current or reduce duty cycle before starting to weld again.
- Do not block or filter airflow to unit.



STATIC (ESD) can damage PC boards.

- Put on grounded wrist strap BEFORE handling boards or parts.
- Use proper static-proof bags and boxes to store, move, or ship PC boards.



MOVING PARTS can cause injury.

- · Keep away from moving parts.
- Keep away from pinch points such as drive rolls



WELDING WIRE can cause injury.

- Do not press gun trigger until instructed to do so.
- Do not point gun toward any part of the body, other people, or any metal when threading welding wire.



MOVING PARTS can cause injury.

- Keep away from moving parts such as fans.
- Keep all doors, panels, covers, and guards closed and securely in place.



H.F. RADIATION can cause interference.

- High-frequency (H.F.) can interfere with radio navigation, safety services, computers, and communications equipment.
- Have only qualified persons familiar with electronic equipment perform this installation.
- The user is responsible for having a qualified electrician promptly correct any interference problem resulting from the installation.
- If notified by the FCC about interference, stop using the equipment at once.
- Have the installation regularly checked and maintained.
- Keep high-frequency source doors and panels tightly shut, keep spark gaps at correct setting, and use grounding and shielding to minimize the possibility of interference.



ARC WELDING can cause interference.

- Electromagnetic energy can interfere with sensitive electronic equipment such as computers and computer-driven equipment such as robots.
- Be sure all equipment in the welding area is electromagnetically compatible.
- To reduce possible interference, keep weld cables as short as possible, close together, and down low, such as on the floor.
- Locate welding operation 100 meters from any sensitive electronic equipment.
- Be sure this welding machine is installed and grounded according to this manual.
- If interference still occurs, the user must take extra measures such as moving the welding machine, using shielded cables, using line filters, or shielding the work area.

1-4. California Proposition 65 Warnings

- ▲ Welding or cutting equipment produces fumes or gases which contain chemicals known to the State of California to cause birth defects and, in some cases, cancer. (California Health & Safety Code Section 25249.5 et seq.)
- ▲ Battery posts, terminals and related accessories contain lead and lead compounds, chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. Wash hands after handling.

For Gasoline Engines:

▲ Engine exhaust contains chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm.

For Diesel Engines:

Diesel engine exhaust and some of its constituents are known to the State of California to cause cancer, birth defects, and other reproductive harm.

1-5. Principal Safety Standards

Safety in Welding, Cutting, and Allied Processes, ANSI Standard Z49.1, from American Welding Society, 550 N.W. LeJeune Rd, Miami FL 33126 (phone: 305-443-9353, website: www.aws.org).

Recommended Safe Practices for the Preparation for Welding and Cutting of Containers and Piping, American Welding Society Standard AWS F4.1, from American Welding Society, 550 N.W. LeJeune Rd, Miami, FL 33126 (phone: 305-443-9353, website: www.aws.org).

National Electrical Code, NFPA Standard 70, from National Fire Protection Association, P.O. Box 9101, 1 Battery March Park, Quincy, MA 02269–9101 (phone: 617–770–3000, website: www.nfpa.org and www. sparky.org).

Safe Handling of Compressed Gases in Cylinders, CGA Pamphlet P-1, from Compressed Gas Association, 1735 Jefferson Davis Highway, Suite 1004, Arlington, VA 22202–4102 (phone: 703–412–0900, website: www.cganet.com).

Code for Safety in Welding and Cutting, CSA Standard W117.2, from Canadian Standards Association, Standards Sales, 178 Rexdale

Boulevard, Rexdale, Ontario, Canada M9W 1R3 (phone: 800–463–6727 or in Toronto 416–747–4044, website: www.csa-international.org).

Practice For Occupational And Educational Eye And Face Protection, ANSI Standard Z87.1, from American National Standards Institute, 11 West 42nd Street, New York, NY 10036–8002 (phone: 212–642–4900, website: www.ansi.org).

Standard for Fire Prevention During Welding, Cutting, and Other Hot Work, NFPA Standard 51B, from National Fire Protection Association, P.O. Box 9101, 1 Battery March Park, Quincy, MA 02269–9101 (phone: 617–770–3000, website: www.nfpa.org and www. sparky.org).

OSHA, Occupational Safety and Health Standards for General Industry, Title 29, Code of Federal Regulations (CFR), Part 1910, Subpart Q, and Part 1926, Subpart J, from U.S. Government Printing Office, Superintendent of Documents, P.O. Box 371954, Pittsburgh, PA 15250 (there are 10 Regional Offices—phone for Region 5, Chicago, is 312–353–2220, website: www.osha.gov).

1-6. EMF Information

Considerations About Welding And The Effects Of Low Frequency Electric And Magnetic Fields

Welding current, as it flows through welding cables, will cause electromagnetic fields. There has been and still is some concern about such fields. However, after examining more than 500 studies spanning 17 years of research, a special blue ribbon committee of the National Research Council concluded that: "The body of evidence, in the committee's judgment, has not demonstrated that exposure to power-frequency electric and magnetic fields is a human-health hazard." However, studies are still going forth and evidence continues to be examined. Until the final conclusions of the research are reached, you may wish to minimize your exposure to electromagnetic fields when welding or cutting.

To reduce magnetic fields in the workplace, use the following procedures:

- 1. Keep cables close together by twisting or taping them.
- 2. Arrange cables to one side and away from the operator.
- 3. Do not coil or drape cables around your body.
- Keep welding power source and cables as far away from operator as practical.
- Connect work clamp to workpiece as close to the weld as possible.

About Pacemakers:

Pacemaker wearers consult your doctor first. If cleared by your doctor, then following the above procedures is recommended.

SECTION 2 – CONSIGNES DE SÉCURITÉ – À LIRE AVANT UTILISATION

som fre 8/03

2-1. Signification des symboles



Signifie « Mise en garde. Faire preuve de vigilance. » Cette procédure présente des risques identifiés par les symboles adjacents aux directives.

▲ Identifie un message de sécurité particulier.

I Signifie « NOTA » ; n'est pas relatif à la sécurité.



Ce groupe de symboles signifie « Mise en garde. Faire preuve de vigilance. » Il y a des dangers liés aux CHOCS ÉLECTRIQUES, aux PIÈCES EN MOUVEMENT et aux PIÈCES CHAUDES. Se reporter aux symboles et aux directives ci-dessous afin de connaître les mesures à prendre pour éviter tout danger.

2-2. Dangers relatifs au soudage à l'arc

- ▲ Les symboles ci-après sont utilisés tout au long du présent manuel pour attirer l'attention sur les dangers potentiels et les identifier. Lorsqu'on voit un symbole, faire preuve de vigilance et suivre les directives mentionnées afin d'éviter tout danger. Les consignes de sécurité énoncées ci-après ne font que résumer le contenu des normes de sécurité mentionnées à la section 2-4. Lire et respecter toutes ces normes.
- ▲ L'installation, l'utilisation, l'entretien et les réparations ne doivent être confiés qu'à des personnes qualifiées.
- ▲ Pendant l'utilisation de l'appareil, tenir à l'écart toute personne, en particulier les enfants.



LES DÉCHARGES ÉLECTRIQUES peuvent être mortelles.

Un simple contact avec des pièces sous tension peut causer une électrocution ou des blessures graves. L'électrode et le circuit de soudage sont sous tension dès que l'appareil est en fonctionnement. Le circuit

d'entrée et les circuits internes de l'appareil sont également sous tension. En soudage semi-automatique ou automatique, le fil, le dévidoir, le logement des galets d'entraînement et les pièces métalliques en contact avec le fil de soudage sont sous tension. Tout matériel mal installé ou mal mis à la terre présente un danger.

- Ne jamais toucher aux pièces électriques sous tension.
- Porter des gants et des vêtements de protection secs et exempts de trous
- S'isoler de la pièce et de la terre au moyen de tapis ou autres dispositifs isolants suffisamment grands pour empêcher tout contact physique avec la pièce ou la terre.
- Ne pas se servir d'une source de courant alternatif dans les zones humides, les endroits confinés ou là où on risque de tomber.
- Ne se servir d'une source de courant alternatif QUE si le procédé de soudage l'exige.
- Si l'utilisation d'une source de courant alternatif s'avère nécessaire, se servir de la fonction de télécommande si l'appareil en est équipé.
- Couper l'alimentation ou arrêter le moteur avant de procéder à l'installation, à la réparation ou à l'entretien de l'appareil. Couper/étiqueter l'alimentation selon la norme OSHA 29 CFR 1910.147 (voir les normes de sécurité).
- Installer et mettre à la terre correctement l'appareil conformément à son manuel d'utilisation et aux codes nationaux, provinciaux et municipaux.
- Toujours vérifier la terre du cordon d'alimentation Vérifier et s'assurer que le fil de terre du cordon d'alimentation est bien raccordé à la borne de terre du sectionneur ou que la fiche du cordon est raccordée à une prise correctement mise à la terre.
- Pour exécuter les branchements d'entrée, fixer d'abord le conducteur de mise à la terre adéquat et contre-vérifier les connexions.
- Vérifier fréquemment le cordon d'alimentation et s'assurer qu'il n'est ni endommagé ni dénudé; le remplacer immédiatement s'il est endommagé – tout câble dénudé peut causer une électrocution.
- Mettre l'appareil hors tension quand on ne l'utilise pas.
- Ne pas utiliser de câbles usés, endommagés, de calibre insuffisant ou mal épissés.
- Ne pas s'enrouler les câbles autour du corps.
- Si la pièce soudée doit être mise à la terre, le faire directement avec un câble distinct.
- Ne pas toucher l'électrode quand on est en contact avec la pièce, la terre ou une électrode d'une autre machine.

- N'utiliser que du matériel en bon état. Réparer ou remplacer sur-lechamp les pièces endommagées. Entretenir l'appareil conformément au présent manuel.
- Porter un harnais de sécurité quand on travaille en hauteur.
- Maintenir solidement en place tous les panneaux et capots.
- Fixer le câble de retour de façon à obtenir un bon contact métal sur métal avec la pièce à souder ou la table de travail, le plus près possible de la soudure.
- Ne pas connecter plus d'une électrode ou plus d'un câble de masse à un même terminal de sortie.

Il subsiste un COURANT CONTINU IMPORTANT dans les convertisseurs après la suppression de l'alimentation électrique.

 Arrêter les convertisseurs, débrancher le courant électrique et décharger les condensateurs d'alimentation selon les instructions énoncées à la section Entretien avant de toucher les pièces.



LES FUMÉES ET LES GAZ peuvent être dangereux.

Le soudage génère des fumées et des gaz dont l'inhalation peut être dangereuse pour la santé.

- Se tenir à distance des fumées et ne pas les inhaler.
- À l'intérieur, ventiler la zone et/ou utiliser un dispositif d'aspiration au niveau de l'arc pour l'évacuation des fumées et des gaz de soudage.
- Si la ventilation est insuffisante, utiliser un respirateur à adduction d'air agréé.
- Lire les fiches techniques de santé-sécurité (FTSS) et les instructions du fabricant concernant les métaux, les consommables, les revêtements, les nettoyants et les dégraisseurs.
- Ne travailler dans un espace clos que s'il est bien ventilé ou porter un respirateur à adduction d'air. Demander toujours à un surveillant dûment formé de se tenir à proximité. Des fumées et des gaz de soudage peuvent se substituer à l'air, abaisser la teneur en oxygène et causer des lésions ou des accidents mortels. S'assurer que l'air est respirable.
- Ne pas souder à proximité d'opérations de dégraissage, de nettoyage ou de pulvérisation. La chaleur et les rayons de l'arc peuvent réagir en présence de vapeurs et former des gaz hautement toxiques et irritants
- Ne pas souder de métaux munis d'un revêtement, tels que la tôle d'acier galvanisée, plombée ou cadmiée, à moins que le revêtement n'ait été enlevé dans la zone de soudage, que l'endroit soit bien ventilé, et si nécessaire, porter un respirateur à adduction d'air. Les revêtements et tous les métaux renfermant ces éléments peuvent dégager des fumées toxiques lorsqu'on les soude.



LES RAYONS DE L'ARC peuvent causer des brûlures oculaires et cutanées.

Le rayonnement de l'arc génère des rayons visibles et invisibles intenses (ultraviolets et infrarouges) susceptibles de causer des brûlures oculaires et cutanées. Des étincelles sont projetées pendant le soudage.

- Porter un masque de soudage muni d'un filtre de la nuance adéquate pour se protéger le visage et les yeux pendant le soudage ou pour regarder (voir les normes de sécurité ANSI Z49.1 et Z87.1).
- Porter des lunettes de sécurité à écrans latéraux sous le masque.
- Utiliser des écrans ou des barrières pour protéger les tiers de l'éclat éblouissant ou aveuglant de l'arc; leur demander de ne pas regarder l'arc.
- Porter des vêtements de protection en matière durable et ignifuge (cuir ou laine) et des chaussures de sécurité.



LE SOUDAGE peut causer un incendie ou une explosion.

Le soudage effectué sur des récipients fermés tels que des réservoirs, des fûts ou des conduites peut causer leur éclatement. Des étincelles peuvent être projetées de l'are de soudure. La projection d'étincelles les

de l'arc de soudure. La projection d'étincelles, les pièces chaudes et les équipements chauds peuvent causer des incendies et des brûlures. Le contact accidentel de l'électrode avec tout objet métallique peut causer des étincelles, une explosion, un surchauffement ou un incendie. Avant de commencer le soudage, vérifier et s'assurer que l'endroit ne présente pas de danger.

- Se protéger et protéger les tiers de la projection d'étincelles et de métal chaud.
- Ne pas souder à un endroit où des étincelles peuvent tomber sur des substances inflammables.
- Placer toutes les substances inflammables à une distance de 10,7 m de l'arc de soudage. En cas d'impossibilité, les recouvrir soigneusement avec des protections agréées.
- Des étincelles et des matières en fusion peuvent facilement passer même par des fissures et des ouvertures de petites dimensions.
- Surveiller tout déclenchement d'incendie et tenir un extincteur à proximité.
- Le soudage effectué sur un plafond, un plancher, une paroi ou une cloison peut déclencher un incendie de l'autre côté.
- Ne pas souder des récipients fermés tels que des réservoirs, des fûts ou des conduites, à moins qu'ils n'aient été préparés conformément à l'AWS F4.1 (voir les normes de sécurité).
- Brancher le câble sur la pièce le plus près possible de la zone de soudage pour éviter que le courant ne circule sur une longue distance, par des chemins inconnus, et ne cause des risques d'électrocution et d'incendie.
- Ne pas utiliser le poste de soudage pour dégeler des conduites gelées.
- En cas de non utilisation, enlever la baguette d'électrode du porteélectrode ou couper le fil au raz du tube-contact.
- Porter des vêtements de protection exempts d'huile tels que des gants en cuir, une chemise en tissu épais, des pantalons sans revers, des chaussures montantes et un masque.
- Avant de souder, retirer tout produit combustible de ses poches, tel qu'un briquet au butane ou des allumettes.



LES PARTICULES PROJETÉES peuvent blesser les yeux.

 Le soudage, le burinage, le passage de la pièce à la brosse métallique et le meulage provoquent l'émission d'étincelles et de particules métalli-

ques. Pendant leur refroidissement, les soudures risquent de projeter du laitier

 Porter des lunettes de sécurité à écrans latéraux agréés, même sous le masque de soudage.



LES ACCUMULATIONS DE GAZ peuvent causer des blessures ou même la mort.

- Couper l'alimentation en gaz protecteur en cas de non utilisation.
- Veiller toujours à bien ventiler les espaces confinés ou porter un respirateur à adduction d'air agréé.



LES PIÈCES CHAUDES peuvent causer des brûlures graves.

- Ne pas toucher les pièces chaudes à main nue.
- Prévoir une période de refroidissement avant d'utiliser le pistolet ou la torche.



LES CHAMPS MAGNÉTIQUES peuvent perturber le fonctionnement des stimulateurs cardiaques.

- Les personnes qui portent un stimulateur cardiaque doivent se tenir à distance.
- Ils doivent consulter leur médecin avant de s'approcher d'un lieu où on exécute des opérations de soudage à l'arc, de gougeage ou de soudage par points.



LE BRUIT peut affecter l'ouïe.

Le bruit de certains processus et équipements peut affecter l'ouïe.

 Porter des protecteurs d'oreille agréés si le niveau sonore est trop élevé.



Les BOUTEILLES endommagées peuvent exploser.

Les bouteilles de gaz protecteur contiennent du gaz sous haute pression. Toute bouteille endommagée peut exploser. Comme les bouteilles de gaz font normalement partie du procédé de soudage, les

manipuler avec précaution.

- Protéger les bouteilles de gaz comprimé de la chaleur excessive, des chocs mécaniques, du laitier, des flammes nues, des étincelles et des arcs
- Placer les bouteilles debout en les fixant dans un support stationnaire ou dans un porte-bouteilles pour les empêcher de tomber ou de se renverser.
- Tenir les bouteilles éloignées des circuits de soudage ou autres circuits électriques.
- Ne jamais poser une torche de soudage sur une bouteille de gaz.
- Ne jamais mettre une électrode de soudage en contact avec une bouteille de gaz.
- Ne jamais souder une bouteille contenant du gaz sous pression elle risquerait d'exploser.
- N'utiliser que les bouteilles de gaz protecteur, régulateurs, tuyaux et raccords adéquats pour l'application envisagée; les maintenir en bon état, ainsi que les pièces connexes.
- Détourner la tête lorsqu'on ouvre la soupape d'une bouteille.
- Laisser le capuchon protecteur sur la soupape, sauf en cas d'utilisation ou de branchement de la bouteille
- Lire et suivre les instructions concernant les bouteilles de gaz comprimé, les équipements associés et les publications P-1 de la CGA, mentionnées dans les normes de sécurité.

2-3. Autres symboles relatifs à l'installation, au fonctionnement et à l'entretien de l'appareil.



Risque D'INCENDIE OU D'EXPLO-SION

- Ne pas placer l'appareil sur une surface inflammable, ni au-dessus ou à proximité d'elle.
- Ne pas installer l'appareil à proximité de produits inflammables.
- Ne pas surcharger l'installation électrique s'assurer que l'alimentation est correctement dimensionnée et protégée avant de mettre l'appareil en service.



LA CHUTE DE L'APPAREIL peut blesser.

- N'utiliser que l'anneau de levage pour lever l'appareil. NE PAS utiliser le chariot, les bouteilles de gaz ou tout autre accessoire.
- Utiliser un engin de capacité adéquate pour lever l'appareil.
- Si on utilise un chariot élévateur pour déplacer l'unité, s'assurer que les fourches sont suffisamment longues pour dépasser du côté opposé de l'appareil.



L'EMPLOI EXCESSIF peut FAIRE SURCHAUFFER L'ÉQUIPEMENT.

- Prévoir une période de refroidissement ; respecter le cycle opératoire nominal.
- Réduire le courant ou le cycle opératoire avant de reprendre le soudage.
- Ne pas obstruer les orifices ou filtrer l'alimentation en air du poste.



LES CHARGES ÉLECTROSTATI-QUES peuvent endommager les circuits imprimés.

- Mettre un bracelet antistatique AVANT de manipuler des cartes ou des pièces.
- Utiliser des pochettes et des boîtes antistatiques pour stocker, déplacer ou expédier des cartes de circuits imprimés.



LES PIÈCES MOBILES peuvent causer des blessures.

- Se tenir à l'écart des pièces mobiles.
- Se tenir à l'écart des points de coincement tels que les dévidoirs.



LES FILS DE SOUDAGE peuvent causer des blessures.

- Ne pas appuyer sur la gâchette avant d'en avoir reçu l'instruction.
- Ne pas diriger le pistolet vers soi, vers d'autres personnes ou vers toute pièce mécanique en engageant le fil de soudage.



LES ORGANES MOBILES peuvent causer des blessures.

- Se tenir à l'écart des organes mobiles comme les ventilateurs.
- Maintenir fermés et bien fixés les portes, panneaux, recouvrements et dispositifs de protection.



LE RAYONNEMENT HAUTE FRÉ-QUENCE (H. F.) risque de causer des interférences.

- Le rayonnement haute fréquence peut causer des interférences avec les équipements de radionavigation et de communication, les services de sécurité et les ordinateurs.
- Ne demander qu'à des personnes qualifiées familiarisées avec les équipements électroniques de faire fonctionner l'installation.
- L'utilisateur est tenu de faire corriger rapidement par un électricien qualifié les interférences causées par l'installation.
- Si la Federal Communications Commission signale des interférences, arrêter immédiatement l'appareil.
- Faire régulièrement contrôler et entretenir l'installation.
- Maintenir soigneusement fermés les panneaux et les portes des sources de haute fréquence, maintenir le jeu d'éclatement au réglage adéquat et utiliser une terre et un blindage pour réduire les interférences éventuelles.



LE SOUDAGE À L'ARC peut causer des interférences.

- L'énergie électromagnétique peut causer des interférences avec l'équipement électronique sensible tel que les ordinateurs et l'équipement commandé par ordinateur tel que les robots.
- Veiller à ce que tout l'équipement de la zone de soudage soit compatible au point de vue électromagnétique.
- Pour réduire la possibilité d'interférence, maintenir les câbles de soudage aussi courts que possible, les grouper, et les poser aussi bas que possible (par ex. : à terre).
- Veiller à souder à une distance de 100 mètres de tout équipement électronique sensible.
- Veiller à ce que le poste de soudage soit posé et mis à la terre conformément au présent manuel.
- En cas d'interférences après exécution des directives précédentes, il incombe à l'utilisateur de prendre des mesures supplémentaires telles que le déplacement du poste, l'utilisation de câbles blindés, l'utilisation de filtres de ligne ou la pose de protecteurs dans la zone de travail.



LES CHAMPS MAGNÉTIQUES peuvent affecter les stimulateurs cardiaques.

- Porteurs de stimulateur cardiaque, restez à distance.
- Les porteurs d'un stimulateur cardiaque doivent d'abord consulter leur médecin avant de s'approcher des opérations de soudage à l'arc, de gougeage ou de soudage par points.

2-4. Principales normes de sécurité

Safety in Welding, Cutting, and Allied Processes, norme ANSI Z49.1, de l'American Welding Society, 550 N.W. LeJeune Rd, Miami FL 33126 (téléphone: (305) 443–9353, site Web: www.aws.org).

Recommended Safe Practices for the Preparation for Welding and Cutting of Containers and Piping, norme American Welding Society AWS F4.1, de l'American Welding Society, 550 N.W. LeJeune Rd, Miami, FL 33126 (téléphone : (305) 443–9353, site Web : www.aws.org).

National Electrical Code, norme NFPA 70, de la National Fire Protection Association, P.O. Box 9101, 1 Battery March Park, Quincy, MA 02269–9101 (téléphone: (617) 770–3000, sites Web: www.nfpa.org et www.sparky.org).

Safe Handling of Compressed Gases in Cylinders, brochure CGA P–1, de la Compressed Gas Association, 1735 Jefferson Davis Highway, Suite 1004, Arlington, VA 22202–4102 (téléphone : (703) 412–0900, site Web : www.cganet.com).

Code for Safety in Welding and Cutting, norme CSA W117.2, de la Canadian Standards Association, Standards Sales, 178 boulevard

Rexdale, Rexdale (Ontario) Canada M9W 1R3 (téléphone: (800) 463–6727ou à Toronto: (416) 747–4044, site Web: www.csa-international.org).

Practice For Occupational And Educational Eye And Face Protection, norme ANSI Z87.1, de l'American National Standards Institute, 11 West 42nd Street, New York, NY 10036–8002 (téléphone : (212) 642–4900, site Web : www.ansi.org).

Standard for Fire Prevention During Welding, Cutting, and Other Hot Work, norme NFPA 51B, de la National Fire Protection Association, P.O. Box 9101, 1 Battery March Park, Quincy, MA 02269–9101 (téléphone: (617) 770–3000, site Web: www.nfpa.org et www.sparky.org).

OSHA, Occupational Safety and Health Standards for General Industry, Title 29, Code of Federal Regulations (CFR), Part 1910, Subpart Q, and Part 1926, Subpart J, de l'U.S. Government Printing Office, Superintendent of Documents, P.O. Box 371954, Pittsburgh, PA 15250 (il y a 10 bureaux régionaux – Téléphone pour la Région 5, Chicago: (312) 353–2220, site Web: www.osha.gov).

2-5. Information sur les champs électromagnétiques

Données sur le soudage électrique et les effets des champs magnétiques basse fréquence sur l'organisme

En parcourant les câbles de soudage, le courant crée des champs électromagnétiques. Les effets potentiels de tels champs restent préoccupants. Cependant, après avoir examiné plus de 500 études qui ont été faites pendant une période de recherche de 17 ans, un comité de spécialistes du National Research Council a conclu : « L'accumulation de preuves n'a pas démontré que l'exposition aux champs magnétiques et aux champs électriques à haute fréquence constitue un risque pour la santé humaine ». Toutefois, les études et l'examen des preuves se poursuivent. En attendant les conclusions finales de la recherche, il serait souhaitable de réduire l'exposition aux champs électromagnétiquespendant le soudage ou le coupage.

Afin de réduire les champs électromagnétiques en milieu de travail, respecter les consignes suivantes :


- Garder les câbles ensemble en les torsadant ou en les fixant avec du ruban adhésif.
- 2. Mettre tous les câbles du côté opposé à l'opérateur.
- 3. Ne pas s'enrouler les câbles autour du corps.
- 4. Garder le poste de soudage et les câbles le plus loin possible de soi.
- 5. Placer la pince de masse le plus près possible de la zone de soudage.

Consignes relatives aux stimulateurs cardiaques :

Les personnes qui portent un stimulateur cardiaque doivent avant tout consulter leur médecin. Si ce dernier les déclare aptes, il leur est recommandé de respecter les consignes ci-dessus.

SECTION 3 – DEFINITIONS


3-1. General Precautionary Label



Warning! Watch Out! There are possible hazards as shown by the symbols.


- Electric shock from welding electrode or wiring can kill.
- 1.1 Wear dry insulating gloves. Do not touch electrode with bare hand. Do not wear wet or damaged gloves.
- 1.2 Protect yourself from electric shock by insulating yourself from work and ground.
- 1.3 Disconnect input plug or power before working on machine.
- 2 Breathing welding fumes can be hazardous to your health.
- 2.1 Keep your head out of the
- 2.2 Use forced ventilation or local exhaust to remove the fumes.
- 2.3 Use ventilating fan to remove fumes.
- Welding sparks can cause explosion or fire.
- 3.1 Keep flammables away from welding. Do not weld near flammables.
- 3.2 Welding sparks can cause fires. Have a fire extinguisher nearby, and have a watchperson ready to use it.
- 3.3 Do not weld on drums or any closed containers.
- 4 Arc rays can burn eyes and injure skin.
- 4.1 Wear hat and safety glasses. Use ear protection and button shirt collar. Use welding helmet with correct shade of filter. Wear complete body protection.
- 5 Become trained and read the instructions before working on the machine or welding.
- Do not remove or paint over (cover) the label.

3-2. Input Connection Label



- Warning! Watch Out! There are possible hazards as shown by the symbols.
- Electric shock from wiring can kill.
- 3 Disconnect input plug or power before working on machine.
- 4 Read the Owner's Manual before working on this machine.
- 5 Consult rating label for input power requirements, and check power available at the job site – they must match.
- 6 Read Owner's Manual and inside labels for connection points and procedures.
- 7 Move jumper links as shown on inside label to match voltage at job site.
- 8 Having a loop of extra length, connect grounding conductor first.
- Connect line input conductors as shown on inside label – double-check all connections, jumper link positions, and input voltage before applying power.


3-3. Electric Shock And Airflow Label



- Warning! Watch Out! There are possible hazards as shown by the symbols.
- Electric shock from wiring and exposed weld terminals can kill
- 3 Close door before turning on unit.

/06


3-4. Nameplate Safety Symbols



- 1 Warning! Watch Out! There are possible hazards as shown by the symbols.
- 2 Electric shock from welding electrode or wiring can kill.
- 3 Sparks from arcing electrode can cause explosion or fire – disconnect cable for process not in use.
- 4 Read Owner's Manual for connection procedures.
- 5 Electric shock from wiring can kill
- 6 Disconnect input power before working on unit or making terminal strip connections.

Nameplate D-179 389

3-5. Manufacturer's Rating Label For CE Products



For label location see Section 4-4.

3-6. Symbol Definitions

NOTE Some symbols are found only on CE products.


Α	Amperage	V	Voltage	Hz	Hertz	===	Direct Current (DC)
\sim	Alternating Current (AC)	0	Panel/Local		Line Connection	3∕	Three Phase
→	Output		On	← ∨	Voltage Input	0	Off
<u></u>	Submerged Arc Welding (SAW)		Read Operator's Manual	7	Remote	X	Duty Cycle
%	Percent	Uo	Rated No-Load Voltage (Average)	U₁	Rated Supply Voltage	0 0	Circuit Breaker
U ₂	Conventional Load Voltage	I ₂	Rated Welding Current	(Protective Earth (Ground)	I _{1max}	Rated Maximum Supply Current
I _{1eff}	Maximum Effective Supply Current	<u>~</u> ₩₩	3-Phase Power Source With AC/DC Output	ŧ	Temperature	**	Ventilating And Air Circulating Fan
·)	Increase	IP	Degree Of Protection		Air Carbon Arc Cutting (CAC-A)	<u></u>	Shielding Metal Arc Welding (SMAW)
<u></u>	Gas Metal Arc Welding GMAW)						

SECTION 4 - INSTALLATION


4-1. Specifications

Model	Rated Welding Output		Max OCV-DC	Amperes Input at Rated Load Output, 60 Hz, Three-Phase		Amperes Input at Rated Load Output, 50 Hz, Three-Phase						
		_		230 V	460 V	575 V	380 V	400 V	440 V	KVA	KW	
1000	1000 A @ 44 Volts DC, 100%	100 – 1250 A In CC Mode	66 VDC	180 5.8*	90 2.9*	72 2.4*				73 3.2*	53 0.5*	
Amp	Duty Cycle	10 – 60 V In CV Mode	66 VDC	0.0						0		
1250	900 A @ 44	100 – 1250 A In CC Mode	00.1/D0	66 VDC				101 5.2*	96 5.0*	87 4.5*	66.3 3.4*	48.4 0.56*
Amp Volts DC, 100% Duty Cycle		10 – 60 V In CV Mode	66 VDC				0.2	0.0		3. 1	0.00	
*While idli	ng	1		1		1	1	1				

4-2. Duty Cycle And Overheating




4-3. Volt-Ampere Curves




va_curve1 - 4/95 - ST-199 986-A / ST-190 973


Selecting A Location




4-5. Dimensions And Weights



4-6. Tipping



4-7. 115 VAC Receptacle And Circuit Breakers



4-8. Weld Output Terminals And Selecting Cable Sizes





▲ ARC WELDING can cause Electromagnetic Interference.

To reduce possible interference, keep weld cables as short as possible, close together, and down low, such as on the floor. Locate welding operation 100 meters from any sensitive electronic equipment. Be sure this welding machine is installed and grounded according to this manual. If interference still occurs, the user must take extra measures such as moving the welding machine, using shielded cables, using line filters, or shielding the work area.


			Total Cabl	e (Copper)	Length In	Weld Circui	t Not Excee	eding	
		100 ft (30	m) Or Less	150 ft (45 m)	200 ft (60 m)	250 ft (70 m)	300 ft (90 m)	350 ft (105 m)	400 ft (120 m)
Turn Off power before connecting to weld output terminals.	Welding Amperes	10 – 60% Duty Cycle	60 – 100% Duty Cycle	10 – 100% Duty Cycle					
	100	4	4	4	3	2	1	1/0	1/0
	150	3	3	2	1	1/0	2/0	3/0	3/0
	200	3	2	1	1/0	2/0	3/0	4/0	4/0
	250	2	1	1/0	2/0	3/0	4/0	2-2/0	2-2/0
Positive \ Negative	300	1	1/0	2/0	3/0	4/0	2-2/0	2-3/0	2-3/0
Low \ Inductance Positive	350	1/0	2/0	3/0	4/0	2-2/0	2-3/0	2-3/0	2-4/0
+ High Inductance	400	1/0	2/0	3/0	4/0	2-2/0	2-3/0	2-4/0	2-4/0
+	500	2/0	3/0	4/0	2-2/0	2-3/0	2-4/0	3-3/0	3-3/0
Positive Low Inductance	600	3/0	4/0	2-2/0	2-3/0	2-4/0	3-3/0	3-4/0	3-4/0
used for all applications.	700	4/0	2-2/0	2-3/0	2-4/0	3-3/0	3-4/0	3-4/0	4-4/0
Positive High Inductance	800	4/0	2-2/0	2-3/0	2-4/0	3-4/0	3-4/0	4-4/0	4-4/0
used for GTAW (TIG) And SMAW (Stick) applications.	900	2-2/0	2-3/0	2-4/0	3-3/0	3-4/0	4-4/0	4-4/0	
	1000	2-2/0	2-3/0	2-4/0	3-3/0	4-3/0	4-4/0		1
	1250	2-3/0	2-4/0	3-3/0	4-3/0	4-4/0		1	

*Weld cable size (AWG) is based on either a 4 volts or less drop or a current density of at least 300 circular mils per ampere. Contact your distributor for the mm² equivalent weld cable sizes.

4-9. Remote 14 Receptacle And Terminal Strip 1T Information

	Socket	Terminal	Information
OUTPUT	Α	Α	24 volts ac. Protected by circuit breaker CB2.
24 VOLTS AC → (CONTACTOR)	В	В	Contact closure to A completes 24 volts ac contactor control circuit.
	С	С	Command reference; 0 to +10 volts dc (CC), +10 volts dc (CV).
REMOTE OUTPUT CONTROL	D	D	Remote control circuit common.
	E	E	0 to +10 volts dc input command signal from remote control.
A /\/ AMPERAGE	F	*	Current feedback; 0 to +10 volts dc, 1 volt per 100 amperes.
A/V VOLTAGE	Н	*	Voltage feedback; 0 to +10 volts dc, 1 volt per 10 arc volts.
OUTPUT	I	I	115 volts, 15 amperes, 60 Hz ac. Protected by circuit breaker CB1.
115 VOLTS AC \longrightarrow (CONTACTOR)	J	J	Contact closure to I completes 115 volts ac contactor control circuit.
GND	K	K	Chassis common.
GND	G	*	Circuit common for 24 and 115 volts ac circuits.
	*	L	
REMOTE POWER ON/OFF	*	М	To remote On/Off switch.
DEMOTE VOLTAGE GENOING	*	N	Voltage sensing signal from Negative (–) weld output terminal.
REMOTE VOLTAGE SENSING	*	Р	Voltage sensing signal from Positive (+) weld output terminal.
* Not Used		1	

4-10. Connecting Remote Control



4-11. Electrical Service Guide

A. 1000 Ampere Rated Welding Output

		60 Hz	
Input Voltage	230	460	575
Input Amperes At Rated Output	180	90	72
Max Recommended Standard Fuse Rating In Amperes ¹			
Time-Delay ²	225	110	90
Normal Operating ³	250	125	110
Min Input Conductor Size In AWG ⁴	3/0	3	4
Max Recommended Input Conductor Length In Feet (Meters)	204 (62)	337 (103)	438 (134)
Min Grounding Conductor Size In AWG ⁴	4	6	6

Reference: 1999 National Electrical Code (NEC)


- 1 Consult factory for circuit breaker applications.
- 2 "Time-Delay" fuses are UL class "RK5" .
- 3 "Normal Operating" (general purpose no intentional delay) fuses are UL class "K5" (up to and including 60 amp), and UL class "H" (65 amp and above).
- 4 Conductor data in this section specifies conductor size (excluding flexible cord or cable) between the panelboard and the equipment per NEC Table 310.16. If a flexible cord or cable is used, minimum conductor size may increase. See NEC Table 400.5(A) for flexible cord and cable requirements.

B. 900 Ampere Rated Welding Output


		50 Hz	
Input Voltage	380	400	440
Input Amperes At Rated Output	101	96	87
Max Recommended Standard Fuse Rating In Amperes ¹			
Time-Delay ²	125	110	100
Normal Operating ³	150	150	125
Min Input Conductor Size In AWG ⁴	2	3	3
Max Recommended Input Conductor Length In Feet (Meters)	353 (108)	325 (99)	393 (120)
Min Grounding Conductor Size In AWG ⁴	6	6	6

Reference: 1999 National Electrical Code (NEC)


- 1 Consult factory for circuit breaker applications.
- 2 "Time-Delay" fuses are UL class "RK5".
- 3 "Normal Operating" (general purpose no intentional delay) fuses are UL class "K5" (up to and including 60 amp), and UL class "H" (65 amp and above).
- 4 Conductor data in this section specifies conductor size (excluding flexible cord or cable) between the panelboard and the equipment per NEC Table 310.16. If a flexible cord or cable is used, minimum conductor size may increase. See NEC Table 400.5(A) for flexible cord and cable requirements.



4-13. Connecting Input Power



Tools Needed:



- ▲ Installation must meet all National and Local Codes have only qualified persons make this installation.
- ▲ Disconnect and lockout/tagout input power before connecting input conductors from unit.
- ▲ Make input power connections to the welding power source first.
- Always connect green or green/ yellow conductor to supply grounding terminal first, and never to a line terminal.

See rating label on unit and check input voltage available at site.

 Input Power Conductors (Customer Supplied Cord)

Select size and length of conductors using Section 4-11. Conductors must comply with national, state, and local electrical codes. If applicable, use lugs of proper amperage capacity and correct hole size.

Welding Power Source Input Power Connections

2 Strain Relief

Route conductors (cord) through strain relief and tighten screws.

- 3 Machine Grounding Terminal
- 4 Green Or Green/Yellow Grounding Conductor
- 5 Reed Switch (Ground Current Sensor) (Optional)

Connect green or green/yellow grounding conductor to welding power source grounding terminal first. If unit is equipped with optional ground current sensor, route grounding conductor through reed switch two times and connect to grounding terminal.

- 6 Welding Power Source Line Terminals
- 7 Input Conductors L1 (U), L2 (V) And L3 (W)

Connect input conductors L1 (U), L2 (V) and L3 (W) to welding power source line terminals.

Close and secure access door on welding power source.

Disconnect Device Input Power Connections

- B Disconnect Device (switch shown in OFF position)
- 9 Disconnect Device (Supply) Grounding Terminal

Connect green or green/yellow grounding conductor to disconnect device grounding terminal first.

10 Disconnect Device Line Terminals

Connect input conductors L1 (U), L2 (V) And L3 (W) to disconnect device line terminals.

11 Overcurrent Protection


Select type and size of overcurrent protection using Section 4-11 (fused disconnect switch shown).

Close and secure door on line disconnect device. Remove lockout/tagout device, and place switch in the On position.

Ref. 800 103-C / Ref. 802 295

Notes	
Work like a Pro	J
Pros weld and cut	
safely. Read the	
safety rules a the beginning	
of this manua	

SECTION 5 – OPERATION



1 Arc Force (Dig) Control

Control increases SMAW short-circuit amperage which allows the operator to use a very short arc length without sticking the electrode.

Set control at 0 for normal welding amperage. Turn clockwise to increase short-circuit amperage.

2 Process Selector Switch

- CV-Sub-Arc Mode For SAW (Sub-Arc) applications requiring 1/16 in dia and larger welding wire.
- CC Mode For SMAW (Stick), GTAW (TIG) – scratch start only, or SAW (Sub-Arc) applications. NOTE: For best results, use the Positive (+) High Inductance weld output terminal (see Section 4-8) for SMAW or GTAW welding.
- CV-FCAW Mode For FCAW (Flux Cored) or SAW (Sub-Arc) applications requiring 1/16 in dia or smaller welding wire.

3 Amperage/Voltage Adjustment Control

When Process Selector switch is in the Constant Current position, turn control clockwise to increase amperage. Read amperage from outer scale of control. When Process Selector switch is in the Constant Voltage position, turn control clockwise to increase voltage. Voltmeter value changes as control knob is turned. Control can be adjusted while welding.

4 Digital Meters

With Process Selector switch in the Constant Current position, digital meters will read 0 (zero) with contactor off. Digital meters will display actual output voltage and amperage with contactor on.

With Process Selector switch in the Constant Voltage position, voltmeter displays preset voltage with contactor off. Voltmeter and ammeter display actual output voltage and amperage with contactor on.

- 5 Power Switch With Indicator Light
- 6 High Temperature Shutdown Light

- 7 Remote Amperage/Voltage Control Switch
- For front panel control, place switch in Panel position. With Control switch in the Panel position and Process switch in the CC position, Hot Start is energized for ACA (Air Carbon Arc Gouging) and SMAW (Stick) welding. When Hot Start is energized, higher short-circuit amperage helps arc starting. After arc starts, the Amperage/Voltage control setting determines weld amperage.
- For remote control, place switch in Remote position, and connect remote device (see Section 4-10). NOTE: Hot Start is not energized when switch is in the Remote position.


8 Output Switch (Contactor)

For front panel control of output, place switch in Panel position. For remote control of output, place switch in Remote position, and connect remote device (see Section 4-10).


- Weld output studs are energized only when Output switch is in On position, or while welding.
- Turn Off power before connecting remote device.

SECTION 6 – MAINTENANCE & TROUBLESHOOTING

6-1. Routine Maintenance



6-2. Fuse F1



6-3. Troubleshooting











Trouble	Remedy			
No weld output; unit completely inoperative; pilot light PL1 off.	Place line disconnect device in On position (see Section 4-13).			
	Check for open line fuse(s), and replace if open (see Section 4-13).			
	Check for proper input power connections (see Section 4-13).			
	Check for proper jumper link position (see Section 4-13).			
	Check fuse F1, and replace if necessary (see Section 6-2).			
No weld output; pilot light PL1 on.	Unit overheated. Allow unit to cool with fan On (see Section 4-2).			
	If using remote control, place Output (Contactor) switch in Remote 14 position, and connect remote control (see Sections 4-9 and 4-10). If remote is not being used, place switch in On position (see Section 5-1).			
	Check, repair, or replace remote control.			
No weld output; power switch pilot light	Check for proper input power connections (see Section 4-13).			
on; fan off.	Check for open line fuse(s), and replace if open, or reset circuit breaker (see Section 4-13).			
	Turn power switch off then back on. If no output condition remains, have Factory Authorized Service agent check SCR's.			
Limited weld output and low	Check position of Remote Amperage/Voltage Control switch (see Section 5-1).			
open-circuit voltage.	Check for open line fuse(s), and replace if open (see Section 4-13).			
	Check for proper input power connections (see Section 4-13).			
	Check for proper jumper link position (see Section 4-13).			
	Clean and tighten all weld output connections.			
Unit provides only maximum or	Have Factory Authorized Service Agent check control board PC1 and hall device HD1.			
minimum weld output.	Check position of Remote Amperage/Voltage Control switch (see Section 5-1).			
Erratic or improper weld output.	Use proper size and type of weld cable (see Section 4-8).			
	Clean and tighten all weld connections.			
	Check wire feeder installation according to Owner's Manual.			
	Check position of Process selector switch (see Section 5-1).			
	Have Factory Authorized Service Agent check control board PC1 and hall device HD1.			
No 115 volts ac output at duplex receptacle, Remote 14 receptacle, or terminal strip 1T.	Reset circuit breaker CB1 (see Section 4-7).			
No 24 volts ac output at Remote 14 receptacle or terminal strip 1T.	Reset circuit breaker CB2 (see Section 4-7).			
Fan not operating. Note: fan only runs	Check for and remove anything blocking fan movement.			
when cooling is necessary.	Have Factory Authorized Service Agent check fan motor.			
Wandering arc; poor control of arc	Reduce gas flow rate.			
direction.	Select proper size tungsten.			
	Properly prepare tungsten.			
Tungsten electrode oxidizing and not	Shield weld zone from drafts.			
remaining bright after conclusion of weld.	Increase postflow time.			
	Check and tighten all gas fittings.			
	Properly prepare tungsten.			
	Check for water in torch, and repair torch if necessary. See torch Owner's Manual.			
Digital meter not working properly.	Have Factory Authorized Service Agent check control board PC1 and connections, and replace if necessary.			

SECTION 7 – ELECTRICAL DIAGRAMS




Figure 7-1. Circuit Diagram for 60 HZ Model





Figure 7-2. Circuit Diagram for 50 HZ Model

SECTION 8 – PARTS LIST



Item No.	Dia. Mkgs.	Part No.	Description Quantity
			8-1. Main Assembly
		+179 432 .	,
			COVER, top
_			. BAFFLE, air
_			BAR, mtg lift eye
<u>_</u>			GASKET, lift eye
8		162 830 .	. LIFT EYE
			. SCREW, .312-18 x 1.750hexhd gr 5 2
9			. STAND-OFF SUPPORT, pc card 4
			. BRACKET, mtg LEM 1
	HD1		
	PLG14		. HOUSING PLUG PINS & SKTS
			BUS BAR, stabilizer
	Z1		STABILIZER 1
	C21-23		. CAPACITOR
-	T2		TRANSFORMER, control 50VA 24V 230/400/373 (00Hz)
			PRIMARY BOX, (includes)
			NUT, 10-32 brs
			STUD, pri bd brs 10-32 x 1.375
			LINK, jumper term bd pri
		010 913 .	. WASHER, flat .218 ID brs
			. HOLDER, fuse mintr 1
	F1		. FUSE, crtg .5A 600V time delay 1
	CR4		. SWITCH, reed
	W		. CONTACTOR, size 3-1/2 3P 24VAC
			LABEL, warning electric shock
			. LABEL, general precautionary wordless,intl (CE models only) 2 . BRACKET, contactor mount (50 Hz Models Only) 2
			BRACKET, contactor mount (60 Hz Models Only)
_			. BASE 1
	T1		. TRANSFORMER, pwr main 230/460/575
28	T1		. TRANSFORMER, pwr main 380/400/440
	TP1,2	175 405 .	THERMOSTAT, NC (Included w/T1)
	TP4,5	168 891 .	THERMOSTAT, NC (Included w/T1) (fan control circuit) 2
	PLG6		. CONNECTOR & SOCKETS 1
	RC6		. CONNECTOR & PINS 1
			. HOUSING, plug pin/skt (service kit) 1
			. HOUSING, plug pin/skt (service kit)
			BRACKET, mtg rectifier
			PANEL, front w/components
			RECTIFIER, scr main (Figure 8-3)
	PLG7		. CONNECTOR & PINS
	RC7		CONNECTOR & SOCKETS
		221 050	CAPACITOR ASSEMBLY, (50 Hz Models Only) (includes)
			CAPACITOR ASSEMBLY, (30 112 Models Offly) (includes) 1
			Bus Bar, capacitor 2
	R6	140 002	RESISTOR, ww fxd 10w 500 ohm
			BRACKET, mtg capacitor
			. CONTACTOR ASSEMBLY (50 Hz Models Only)
			. SCREW, .312-18 x 1.75 hex hd-pln gr5 pld 2
		Cround Curre	

[◆] Part of Option 195 048 Ground Current Sensor.

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.

⁺When ordering a component originally displaying a precautionary label, the label should also be ordered.

^{*}Recommended Spare Parts.




Figure 8-2. Panel, Front w/Components (Figure 8-1 Item 32)

OM-2223 Page 30

Figure 8-2. Panel, Front w/Components (Figure 8-1 Item 32)					
1 159 863	ELECTRONICS BOX				
2 PC1 207 035	CIRCUIT CARD ASSY, control (50Hz) 1				
	CIRCUIT CARD ASSY, control (60Hz) 1				
PI G1 158 720	CONNECTOR & SOCKETS, (see Figure 8-3)				
	CONNECTOR & SOCKETS				
	CONNECTOR & SOCKETS				
	CONNECTOR & SOCKETS				
	CONNECTOR & SOCKETS				
	RELAY, encl 24VDC DPDT				
	RELAY, encl 24VAC DPDT				
	CIRCUIT BREAKER, man reset 1P 15A 250VAC				
	RECEPTACLE, str dx grd 2P3W 15A 125V				
/ 191 335	RECEPTACLE/CAPACITOR, w/leads (includes)				
	RCPT w/ SCKTS (service kit)				
	CAPACITOR, cer disc .05 uf 500 VDC strip				
8 190 958	PANEL, front				
	CAPACITOR, cer disc .1uf 500VDC				
10 190 961	TERMINAL, single stud 1				
11 190 960	TERMINAL, double stud 2				
	RESISTOR, WW fxd 30W 200 ohm				
	SPRING, cprsn .600 OD x .072 wire x 1.500 lg				
	PLATE, control lower 1				
15 1T 159 040	BLOCK, term 20A 12P 1				
16 162 828	PANEL, mtg rcpt/terminal strip				
17 070 371	BLANK, snap-in nyl 1.093/1.125mtg hole 1				
18 217 865	LABEL, warning electric shock and reduced air 1				
	LABEL, electric shock/reduce air flow (CE models only) 1				
19 172 587	COVER, output stud 1				
	CLIP, spring				
	NUT, 10-32 brs				
	WASHER, flat .218 ID brs 1				
	STUD, pri bd brs 10-32 x 1.592 1				
	SWITCH, tgl DPDT 15A 125VAC On-Off-On				
	SWITCH, tgl SPDT 15A 125VAC On-None-On				
	POTENTIOMETER, CP std slot 1/T 2W 1K ohm				
	CIRCUIT CARD ASSY, digital meter (60 and 50 Hz Models) 1				
PLG10 153 501	CONNECTOR & SOCKETS				
	CONNECTOR & SOCKETS				
	RELAY, encl 24VDC 3PDT				
	STAND-OFF				
	PANEL, front upper				
	NAMEPLATE, (order by model and serial number)				
30 60 150 000	NAMEPLATE, (order by moder and serial number)				
20 150 000	LED, yellow				
	KNOB, pointer				
	KNOB, pointer				
	SNUBBER , assy				
36 54 011 611	SWITCH, tgl DPDT 15A 125VAC On-None-On 1				

⁺When ordering a component originally displaying a precautionary label, the label should also be ordered.

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.

item	Dia.	Part		
No.	Mkgs.	No.	Description	Quantity

Figure 8-3. Rectifier, SCR Main (Figure 8-1 Item 33)

1 C7-12 048 420 CAPACITOR, cer disc .01uf 1000VDC
2
3
4
5 SCR1-6 148 091 THYRISTOR, SCR 865A 300V hockey puck
6
7
TP3 192 731 THERMOSTAT, rectifier 1
TP6 168 894 THERMOSTAT rectifier (fan control circuit) 1




Figure 8-3. Rectifier, SCR Main

800 696-A

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.

Item	Dia.	Part		
No.	Mkgs.	No.	Description	Quantity

Figure 8-4. Panel, Rear w/Components (Figure 8-1 Item 21)

1	CHAMBER, plenum 14 in/motor mount
2 605 799	BLADE, fan 14 in 5wg 30deg .500 bore CW
3 191 552	PANEL, rear 1
4	HINGE, door primary 2
5	DOOR, primary access 1
6 217 733	LABEL, warning electric shock & input power (EN/FR) 1
6 179 290	LABEL, warning electric shock input connection (CE models only) 1
7 R3 097 459	RESISTOR, WW fxd 375W 20 ohm 1
8 FM 032 605	MOTOR, 1/4HP 230VAC 1625RPM 50/60Hz 1
9 183 167	CONNECTOR, clamp cable 2.000 1





Figure 8-4. Panel, Rear w/Components

+When ordering a component originally displaying a precautionary label, the label should also be ordered.

To maintain the factory original performance of your equipment, use only Manufacturer's Suggested Replacement Parts. Model and serial number required when ordering parts from your local distributor.

Notes



Your distributor also gives you ...

Miller distributor.

Service

You always get the fast, reliable response you need. Most replacement parts can be in your hands in 24 hours.

Support

Need fast answers to the tough welding questions? Contact your distributor. The expertise of the distributor and Miller is there to help you, every step of the way.



Effective January 1, 2005 (Equipment with a serial number preface of "LF" or newer)

This limited warranty supersedes all previous Miller warranties and is exclusive with no other guarantees or warranties expressed or implied.

LIMITED WARRANTY – Subject to the terms and conditions below, Miller Electric Mfg. Co., Appleton, Wisconsin, warrants to its original retail purchaser that new Miller equipment sold after the effective date of this limited warranty is free of defects in material and workmanship at the time it is shipped by Miller. THIS WARRANTY IS EXPRESSLY IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, INCLUDING THE WARRANTIES OF MERCHANTABILITY AND FITNESS.

Within the warranty periods listed below, Miller will repair or replace any warranted parts or components that fail due to such defects in material or workmanship. Miller must be notified in writing within thirty (30) days of such defect or failure, at which time Miller will provide instructions on the warranty claim procedures to be followed.

Miller shall honor warranty claims on warranted equipment listed below in the event of such a failure within the warranty time periods. All warranty time periods start on the date that the equipment was delivered to the original retail purchaser, or one year after the equipment is sent to a North American distributor or eighteen months after the equipment is sent to an International distributor.

- 1. 5 Years Parts 3 Years Labor
 - * Original main power rectifiers
 - Inverters (input and output rectifiers only)
- 2. 3 Years Parts and Labor
 - * Transformer/Rectifier Power Sources
 - * Plasma Arc Cutting Power Sources
 - * Semi-Automatic and Automatic Wire Feeders
 - * Inverter Power Sources (Unless Otherwise Stated)
 - * Water Coolant Systems (Integrated)
 - * Intellitig
 - * Maxstar 150
 - Engine Driven Welding Generators (NOTE: Engines are warranted separately by the engine manufacturer.)
- 3. 1 Year Parts and Labor Unless Specified
 - * DS-2 Wire Feeder
 - Motor Driven Guns (w/exception of Spoolmate Spoolguns)
 - * Process Controllers
 - * Positioners and Controllers
 - * Automatic Motion Devices
 - * RFCS Foot Controls
 - * Induction Heating Power Sources and Coolers
 - * Water Coolant Systems (Non-Integrated)
 - * Flowgauge and Flowmeter Regulators (No Labor)
 - * HF Units
 - * Grids
 - * Maxstar 85, 140
 - * Spot Welders
 - * Load Banks
 - * Arc Stud Power Sources & Arc Stud Guns
 - * Racks
 - * Running Gear/Trailers
 - Plasma Cutting Torches (except APT & SAF Models)
 - * Field Options (NOTE: Field options are covered under True Blue® for the remaining warranty period of the product they are installed in, or for a minimum of one year — whichever is greater.)
- 4. 6 Months Batteries
- 5. 90 Days Parts
 - * MIG Guns/TIG Torches

- * Induction Heating Coils and Blankets
- * APT & SAF Model Plasma Cutting Torches
- * Remote Controls
- * Accessory Kits
- * Replacement Parts (No labor)
- * Spoolmate Spoolguns
- * Canvas Covers

Miller's True Blue® Limited Warranty shall not apply to:

- Consumable components; such as contact tips, cutting nozzles, contactors, brushes, slip rings, relays or parts that fail due to normal wear. (Exception: brushes, slip rings, and relays are covered on Bobcat, Trailblazer, and Legend models.)
- Items furnished by Miller, but manufactured by others, such as engines or trade accessories. These items are covered by the manufacturer's warranty, if any.
- Equipment that has been modified by any party other than Miller, or equipment that has been improperly installed, improperly operated or misused based upon industry standards, or equipment which has not had reasonable and necessary maintenance, or equipment which has been used for operation outside of the specifications for the equipment.

MILLER PRODUCTS ARE INTENDED FOR PURCHASE AND USE BY COMMERCIAL/INDUSTRIAL USERS AND PERSONS TRAINED AND EXPERIENCED IN THE USE AND MAINTENANCE OF WELDING EQUIPMENT.

In the event of a warranty claim covered by this warranty, the exclusive remedies shall be, at Miller's option: (1) repair; or (2) replacement; or, where authorized in writing by Miller in appropriate cases, (3) the reasonable cost of repair or replacement at an authorized Miller service station; or (4) payment of or credit for the purchase price (less reasonable depreciation based upon actual use) upon return of the goods at customer's risk and expense. Miller's option of repair or replacement will be F.O.B., Factory at Appleton, Wisconsin, or F.O.B. at a Miller authorized service facility as determined by Miller. Therefore no compensation or reimbursement for transportation costs of any kind will be allowed.

TO THE EXTENT PERMITTED BY LAW, THE REMEDIES PROVIDED HEREIN ARE THE SOLE AND EXCLUSIVE REMEDIES. IN NO EVENT SHALL MILLER BE LIABLE FOR DIRECT, INDIRECT, SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES (INCLUDING LOSS OF PROFIT), WHETHER BASED ON CONTRACT, TORT OR ANY OTHER LEGAL THEORY.

ANY EXPRESS WARRANTY NOT PROVIDED HEREIN AND ANY IMPLIED WARRANTY, GUARANTY OR REPRESENTATION AS TO PERFORMANCE, AND ANY REMEDY FOR BREACH OF CONTRACT TORT OR ANY OTHER LEGAL THEORY WHICH, BUT FOR THIS PROVISION, MIGHT ARISE BY IMPLICATION, OPERATION OF LAW, CUSTOM OF TRADE OR COURSE OF DEALING, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR PARTICULAR PURPOSE, WITH RESPECT TO ANY AND ALL EQUIPMENT FURNISHED BY MILLER IS EXCLUDED AND DISCLAIMED BY MILLER IS EXCLUDED AND DISCLAIMED

Some states in the U.S.A. do not allow limitations of how long an implied warranty lasts, or the exclusion of incidental, indirect, special or consequential damages, so the above limitation or exclusion may not apply to you. This warranty provides specific legal rights, and other rights may be available, but may vary from state to state.

In Canada, legislation in some provinces provides for certain additional warranties or remedies other than as stated herein, and to the extent that they may not be waived, the limitations and exclusions set out above may not apply. This Limited Warranty provides specific legal rights, and other rights may be available, but may vary from province to province.





Please complete and retain with your personal records.

Serial/Style Number
(Date which equipment was delivered to original customer.)
Zip



Contact a DISTRIBUTOR or SERVICE AGENCY near you.

Always provide Model Name and Serial/Style Number.

Contact your Distributor for:	Welding Supplies and Consumables	
	Options and Accessories	
	Personal Safety Equipment	
	Service and Repair	
	Replacement Parts	
	Training (Schools, Videos, Books)	
	Technical Manuals (Servicing Information and Parts)	
	Circuit Diagrams	
	Welding Process Handbooks	
	To locate a Distributor or Service Agency visit www.millerwelds.com or call 1-800-4-A-Miller	
Contact the Delivering Carrier to:	File a claim for loss or damage during shipment.	
	For assistance in filing or settling claims, contact your distributor and/or equipment manufacturer's Transportation Department.	

Miller Electric Mfg. Co.

An Illinois Tool Works Company 1635 West Spencer Street Appleton, WI 54914 USA

International Headquarters-USA
USA Phone: 920-735-4505 Auto-Attended
USA & Canada FAX: 920-735-4134
International FAX: 920-735-4125

European Headquarters – United Kingdom Phone: 44 (0) 1204-593493 FAX: 44 (0) 1204-598066

www.MillerWelds.com

